

Product Change Notification

Issue Date: May 17, 2022

Product Name: IMBA-Q370-R10

Status: Implement on next production

This notice is to inform you of changes to the :

1. IMBA-Q370-R10

Reason for Change

1. Solve the shortage of materials.

Description of Change

1. Change PCB design from R10 to R20.
2. Audio IC change from ALC662 to ALC888
3. VGA IC Change from CH7517A-BF to LT8711V_QFN4
4. USB redriver change ON Semiconductor;NB7NPQ7042 to ASM1562
5. HDMI Shifter IC change from TI:SN75DP139 to ASM1442

Affected Model

Affected Model	New Version
IMBA-Q370-R10	IMBA-Q370-R20

Affected by This Change

- | | | | |
|-----------------------------------------|-------------------------------------|------------------------------------------------|----------------------------------|
| <input type="checkbox"/> Specifications | <input type="checkbox"/> Dimensions | <input checked="" type="checkbox"/> Appearance | <input type="checkbox"/> Package |
| <input type="checkbox"/> Certification | <input type="checkbox"/> Label | <input checked="" type="checkbox"/> BIOS | <input type="checkbox"/> Driver |

For more details please refer to the latest datasheet or visit <http://www.ieiworld.com>.

Best Regards,
 Maoxin Li
 Product Manager
 IEI Integration Corp.